

Attached are several photos, taken in 2024, showing the tremendous disintegration of the east peninsula of the forebay.

One photo is from Niagara Navigator in 2024. The other photos were taken on July 14, 2024, by a professional photographer whom I personally retained and solely paid for.

The purpose is because aerial photos show best what is happening with the pond.